

Next-generation video analytics DWC-XSTD05Bi - fixed lens DWC-XSTD05Mi - vari-focal lens



 $\mathsf{DW}^{\$}\:\mathsf{IP}\:\mathsf{Finder}^{{\scriptscriptstyle\mathsf{TM}}}\:\mathsf{software}$ or directly from the camera's browser menu.

(T10) Moisture Absorber (Recommended)



Remove the Dessicant Pack used for shipping. · Place the new Dessicant Pack as shown in the illustration below. Close the camera control panel tightly.

ESSICANT PAC PACK and

(8)

DESSICANT F


(0)

- Use a PoE Injector (Sold Use a non-PoE Switch to connect separately) to connect data and data using an Ethernet cable and power to the camera using a use a power adapter to power single Ethernet cable. the camera. **◯ ←** □→**∮**-€
- The waterproof cap set comes with two rubber rings. Use the rubber ring best sized for your network cable's diameter.

Cables ø4.5mm ~ ø5.5mm thickness: use the black rubber ring. Cables > Ø5.5mm thickness: use the white rubber ring.

WATERPROOF CAP INSTALLATION

b




Rubber plug

Reset Button

Mounting template

- a camera-wide reset of all the settings, including network settings.



contacts should be facing upward, as shown in the diagram.

0

0

a. Check the box next to the camera. b. Click "Bulk Password Assign" on the left. c. Enter admin/admin for the current username and password. Enter a new username and password to the right. Password must have at least eight (8) characters and at least four (4) combinations of

Download and install the DW IP Finder from the DW website at:

Open the DW IP Finder and click 'Scan Devices' to find the camera

3. A password must be set when connecting to the camera for the first

4. Enter the camera's username and password you setup in the DW IP

Change admin's password Password Retype Password Password Hint

The GUI display may differ by camera models.

[Type the Password] Password requirement: minimum 8 characters with at least three combinations of uppercase letters, lowercase letters, numbers and special characters Acceptable special characters are; \sim `!\$ \(() _ - |{}[]; . ?/

Rev: 11/24

This products is covered by one or more claims of the HEVC NOTE: Patents listed at patentlist.accessadvance.com.

Tel: +1 (866) 446-3595 / (813) 888-9555 Technical Support Hours: 9:00AM - 8:00PM EST, Monday through Friday

NOTE: Please see the full product manual for web viewer setup, functions and camera settings options.

WHAT'S IN THE BOX Screws and Quick Setup and Download Plastic 1 set Guide Anchors - 2pcs Mounting Star Wrench Template Hexagonal wrench 2.0 Waterproof Cap and Rubber Rings (Black: Ø0.15" (Ø4mm), White: Ø0.19" (ø5mm)) NOTE: Download all your support materials and tools in one place 1. Go to: http://www.digital-watchdog.com/resources 2. Search your product by entering the part number in the 'Search by Product' search bar. Results for applicable part numbers will populate automatically based on the part number you enter.
3. Click **'Search'**. All supported materials, including manuals and quick start guide (QSGs) will appear in the results. Attention: This document is intended to serve as a quick reference for the initial set-up. It is recommended of the camera.

that the user read the entire instruction manual for complete and proper installation and usage. STEP 1 - PREPARING TO MOUNT THE CAMERA 1. Install the Dessicant Pack (moisture absorber): • Remove the Dessicant Pack from its shipping packaging. · Using the star wrench, open the camera's control panel on the side

NOTE: The camera will generate enough heat to dry moisture during operation. In case of moisture issues, keep the moisture absorber in the camera up to 6 months. WARNING: Install the moisture absorber when mounting the camera to prevent performance issues and damage to the camera. 2. Mark and drill the necessary holes in the wall or ceiling using the

mounting template sheet or the camera itself. STEP 2 - POWERING THE CAMERA Pass the wires through and make all necessary connections.

Power information Power requirements DC12V, PoE (Adapter not included) DWC-XSTD05Bi: DC: max 7.5W, 625mA, PoE: max 9.5W, 197mA DWC-XSTD05Mi: DC: max 8.5W, 708mA, PoE: max 11W, 229mA Power consumption 328' (100m) Maximum distance RJ45 Connector

Make sure the o-ring (1) is in place between (2) and (3). An outdoor rated sealer is recommended.

1. Secure the camera to the mounting surface using the included screws. 2. Use the rubber plug on the side of the camera as a cable guide to prevent cables from getting caught between the camera and the mounting surface.

STEP 3 - INSTALLING THE CAMERA

4. Remove the protective film from the lens cover. Softly wipe the lens cover with lens tissue or a microfiber cloth with ethanol to remove any dust or smudges left from the installation process. Resetting the camera: Press the reset button for five (5) seconds to initiate



STEP 4 - CABLING

SD Card Slot

STEP 6 - DW® IP FINDER™

http://www.digital-watchdog.com

uppercase and lowercase letters, numbers and special characters. Passwords cannot contain the user ID. d. Click "change" to apply all changes.

STEP 7 - WEB VIEWER

WeDIGITAL

on the network.

time.

Find the camera using the DW IP Finder. 2. Double-click on the camera's view in the results table. Press the 'View Camera Website'.

If you did not setup a new username and password, a message will direct you to setup a new password for the camera to view the video. http://192.168.10.159/ - IP Camera - Internet Explorer

Finder

digital-watchdog.com

Copyright © Digital Watchdog. All rights reserved. Specifications and pricing are subject to change without notice.